To: Stalcup, Dana[Stalcup.Dana@epa.gov]

**Cc:** Jackson, Robert W.[Jackson.Robertw@epa.gov]; Gunn, Gene[gunn.gene@epa.gov]

From: Peterson, Mary

Sent: Fri 8/14/2015 2:56:35 PM
Subject: Region 7 Mine Sites Inventory
Copy of R7 Mine Sites Spreadsheet ver2.xlsx

Dana,

Attached is our completed spreadsheet. As I indicated on the phone yesterday, we do not believe that any of our sites are analogous to the Gold King Mine site and do not pose a threat of catastrophic release. We have a lot of important site work ongoing at several sites and we believe this work can and should continue in order to address exposures. After reviewing the spreadsheet, let me know what additional information you might need.

## Mary P. Peterson, Director

Superfund Division EPA Region 7 11201 Renner Blvd. Lenexa, KS 66219 Office: 913-551-7882 Cell: 816-398-3945



"To safeguard the health of our communities for all generations, we clean up contaminated lands.

In a culture of teamwork and respect, we are efficient, innovative, and fiscally responsible stewards of public trust."